



Inspection Report


Inspection Date: 2017/08/08

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-141		
Year	2006		
Hour (h)	1776	Meter	Working
Serial Number	33343		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		350		


Note for External Appearance
The side cover has cracks


Undercarriage		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The sensor of the swing is not in a good condition


Note for Undercarriage
The rubber shoes have deteriorated over time and are worn


Engine	
Model	D722-KA
Serial Number	5MC589
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The roof is damaged


Note for Engine


Admin No. 2017080018