



# Inspection Report

Inspection Date: 2017/10/10


## Excavators

General Information			
Maker	KOMATSU		
Model Number	PC38UU-3		
Year	2007		
Hour (h)	3271	Meter	Not Working
Serial Number	9819		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		510		

Note for External Appearance
- Repainted - The body has some dents




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- The movement of the upper structure is unchecked - No bucket teeth




Note for Undercarriage




Engine	
Model	3D84E-3MB1
Serial Number	46781
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

Note for Operating Component
- The seat cover is partly cracked - The travel levers are partly damaged



Note for Engine
- The battery is flat - The movement of the engine is unchecked



Admin No. 2017100782