



# Inspection Report

Inspection Date: 2024/11/14

## Wheel Loader

### General Information

Maker	YANMAR
Model Number	V3-6
Year	2012
Hour (h)	2003
Serial Number	61730

### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

### Engine

Model	3TNV88-BNKAH
Serial Number	I9717
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for External Appearance

- The body is rusty and corroded (see photo)



### Note for Upper Structure



### Note for Operating Component



### Note for Undercarriage

- Studless tires: 12.5/70-16 6P.R.  
- The surface of the tires have some cracks



### Note for Engine

- EPA  
- The tip of the muffler is missing



Admin. No. 3000065126

\*This report is only for your reference. We are not responsible for the actual condition of checked item.