



# Inspection Report

Inspection Date: 2019/02/19

## Dozer

### General Information

<b>Maker</b>	MITSUBISHI	
<b>Model Number</b>	BD2H	
<b>Year</b>	1996	
<b>Hour (h)</b>	4108	
<b>Serial Number</b>	HB151006	

### Note for External Appearance



### Upper Structure

<b>Blade Tilt Cylinder</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Lift Arm Cylinder</b>	No oil leak	No oil leak
<b>Blade Angle Cylinder</b>	No oil leak	No oil leak
<b>Travel Motor</b>	No oil leak	No oil leak

### Note for Upper Structure

Operational condition of the upper structure is unchecked



### Undercarriage

	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	500	500
<b>Idler</b>	OK	OK
<b>Shoe Link</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Pin Bush</b>	OK	OK

### Note for Operating Component



### Note for Undercarriage

Traveling motion is unchecked



### Engine

<b>Model</b>	
<b>Serial Number</b>	37476
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Unchecked
<b>Blow-by</b>	Unchecked
<b>Engine Sound</b>	Unchecked
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for Engine

- The battery is flat
- Operational condition of the engine is unchecked



Admin. No. 2019020354

\*This report is only for your reference. We are not responsible for the actual condition of checked item.