

# **Inspection Report**

### Inspection Date: 2018/12/12

## Excavators

| General Information |            |         |
|---------------------|------------|---------|
| Maker               | AIRMAN     |         |
| Model Number        | AX30UR-6   |         |
| Year                | 2010       |         |
| Hour (h)            | 3913 Meter | Working |
| Serial Number       | 35095      |         |

#### Upper Structure


|                  |       | Cylinder |              | Play |
|------------------|-------|----------|--------------|------|
|                  |       | Oil Leak | Scratch/Rust |      |
| Boom             | Left  | No       | No           | No   |
| Boom             | Right | N/A      | No           |      |
|                  | Arm   | No       | No           | No   |
| Bucket           |       | No       | No           | No   |
| Bucket Size (mm) |       | 445      |              |      |

### Undercarriage

| Steel shoes with rubber pads |  |
|------------------------------|--|
| No oil leak                  |  |
| Left                         | Right  |
| 300                          | 300  |
| ОК                           | ОК   |
| ОК                           | NG   |
| ОК                           | ОК   |
|                              | No oil leak<br>Left<br>300<br>OK<br>OK<br>OK<br>OK |

| Engine           |               |
|------------------|---------------|
| Model            | 3TNV88-BSHB   |
| Serial Number    | C6245         |
| Engine Oil Leak  | Oil oozing    |
| Engine Oil Gauge | ОК            |
| Radiator         | Normal        |
| Exhaust Color    | Normal        |
| Blow-by          | No            |
| Engine Sound     | ОК            |
| Hydraulic Pump   | No oil leak   |
| Water Pump       | No water leak |
| Oil Cooler       | Oil oozing    |
| Motor            | No oil leak   |
| Multi Lever      | Oil oozing    |

| Options      |  |  |
|--------------|--|--|
| - CNP        |  |  |
| - Multilever |  |  |
| - Blade      |  |  |
| - Arm Crane  |  |  |
|              |  |  |



| Note for Upper Structure      |  |
|-------------------------------|--|
| The bucket is partly deformed |  |
|                               |  |
|                               |  |
|                               |  |

| Note for Undercarriage |  |
|------------------------|--|
|                        |  |
|                        |  |
|                        |  |
|                        |  |
|                        |  |

| Note for Operating Component |  |
|------------------------------|--|
|                              |  |
|                              |  |
|                              |  |
| Note for Engine              |  |

- Oil leak from around the engine oil

- gauge Oil oozing from under the engine

Admin No.

2018120039

\*This report is only for your reference. We are not responsible for the actual condition of checked item.