

Inspection Report

Inspection Date: 2018/03/01

Excavators

| General Information | | |
|---------------------|------------|---------|
| Maker | KOMATSU | |
| Model Number | PC138US-10 | |
| Year | 2015 | |
| Hour (h) | 1073 Meter | Working |
| Serial Number | 43212 | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|----------|--------------|-----------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | No |
| | Right | No | No | NO |
| | Arm | No | No | No |
| Bucket | | No | No | Unchecked |
| Bucket Size (mm) | | - | | |

Undercarriage

| Shoe Type | Steel shoes with rubber pads | |
|-----------------|------------------------------|-------|
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 500 | 500 |
| Idler | ОК | ОК |
| Sprocket | ОК | ОК |
| Pin Bush | ОК | ОК |
| Upper Roller | ОК | ОК |
| Track Roller | ОК | ОК |
| Shoe Link | ОК | ОК |
| | | |

| Engine | |
|------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | Unchecked |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | No oil leak |
| | |

Options - CAB - Speed changer - Multilever - Air conditioner - Arm Crane - Pipings

Note for External Appearance




Note for Upper Structure

- 3 sides of the arm are reinforced
- No standard bucket

- The skeleton bucket in the picture is included but is not attachable (pin size: 65mm, arm width: 260mm)





Lot No ARA013-0003 Admin No.

2018020310

*This report is only for your reference. We are not responsible for the actual condition of checked item