

Inspection Report

Mini Excavator

| General Information | |
|---------------------|---------|
| Maker | YANMAR |
| Model Number | Vio40-5 |
| Year | 2005 |
| Hour (h) | 3909 |
| Serial Number | 506 |

| Upper Structure | |
|-------------------|-------------------|
| Boom Cylinder | Oil oozing |
| Arm Cylinder | No oil leak |
| Bucket Cylinder | No oil leak |
| Bucket Width (mm) | 600 |
| Swing | Backlash and play |

Operating Component

Speed Pedal Yes

| Undercarriage | | | |
|-----------------|-------------|-------|--|
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 350 | 350 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | NG | |
| Shoe Link | ОК | ОК | |

| Engine | | |
|------------------|--------------------------|--|
| Model | | |
| Serial Number | | |
| Engine Oil Leak | No oil leak | |
| Engine Oil Gauge | ОК | |
| Radiator | Not enough cooling water | |
| Exhaust Color | Normal | |
| Blow-by | No | |
| Engine Sound | ОК | |
| Hydraulic Pump | No oil leak | |
| Water Pump | No water leak | |
| Oil Cooler | No oil cooler | |

Note for External Appearance

Repainted



Note for Upper Structure

- Pipings
- The bucket and arm have plays



Note for Operating Component

Multi leverThe travel lever is deformed

Note for Undercarriage

- Oil oozing from a lower roller - Rubber shoes are deteriorated over time and cracked

Note for Engine

The battery is flat