



# Inspection Report

Inspection Date: 2026/03/04

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC138US-10		
<b>Year</b>	2016		
<b>Hour (h)</b>	4196	<b>Meter</b>	Working
<b>Serial Number</b>	KMTPC245HGA045488		

### Options

- CAB	- Speed changer
- Multilever	- Pippings
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Oil oozing	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)	850			

### Note for External Appearance

- The right cover of the body won't open
- The body has some scratches, rust, and dents



### Undercarriage

<b>Shoe Type</b>	Steel		
<b>Swing Circle</b>	No oil leak		
		Left	Right
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

### Note for Upper Structure

- The arm has been reinforced



### Note for Undercarriage

- The shoes are loose



### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000082599