| Inspection | Date: | 2021/11/19 |
|------------|-------|------------|
| | | |

| General Information | | |
|---------------------|-------------------|---------|
| Maker | KUBOTA | |
| Model Number | U-30-5 | |
| Year | 2011 | |
| Hour (h) | 5381 Meter | Working |
| Serial Number | JKUU0305J00H73483 | |

| Options | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |
| | |
| | |

| Upper Structure | | | | | |
|------------------|-------|----------|--------------|---------|--|
| | | Cylinder | | Play | |
| | | Oil Leak | Scratch/Rust | Flay | |
| Boom - | Left | No | No | Small | |
| | Right | N/A | N/A | Offiaii | |
| Arm | | No | No | Small | |
| Bucket | | No | No | Small | |
| Bucket Size (mm) | | 610 | | | |
| | | | | | |

| | | Oil Leak | Scratch/Rust | |
|------------------|---------|----------|--------------|---------|
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | Offiaii |
| | Arm | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 610 | | |
| | | | | |
| Undercarriage | | | | |
| Sh | ое Туре | Rubber | | |
| | | | | |

| Undercarriage | | |
|-----------------|-------------|-------|
| Shoe Type | Rubber | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 300 | 300 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | NG | NG |
| Shoe Link | OK | ОК |

| Engine | |
|------------------|---------------|
| Model | D1703 |
| Serial Number | BW0285 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | ОК |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

| Note for External Appearance | |
|-----------------------------------------------------------------------------------------------------------------------------------|--|
| The covers are damaged and have some dents The engine cover is broken The canopy is damaged | |



| Note for Undercarriage | |
|----------------------------------------------------------------|--|
| -Oil oozing from 1 of the left and 1 of the right lower rolles | |



