



# Inspection Report

Inspection Date: 2019/02/16

## Dozer

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	D31P-20E
<b>Year</b>	2000
<b>Hour (h)</b>	4865
<b>Serial Number</b>	49222

### Note for External Appearance

The body is rusty



### Upper Structure

<b>Blade Tilt Cylinder</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Lift Arm Cylinder</b>	No oil leak	No oil leak
<b>Blade Angle Cylinder</b>	No oil leak	No oil leak
<b>Travel Motor</b>	No oil leak	No oil leak

### Note for Upper Structure



### Undercarriage

	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	600	600
<b>Idler</b>	OK	OK
<b>Shoe Link</b>	OK	OK
<b>Sprocket</b>	NG	NG
<b>Track Roller</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Pin Bush</b>	OK	OK

### Note for Operating Component



### Note for Undercarriage

- The sprockets are worn
- The right shoe is partly loose
- According to the seller, the track adjusters are broken
- Traveling motion is unchecked because there was not enough space for inspection



### Engine

<b>Model</b>	S4D102E-1-A
<b>Serial Number</b>	26277017
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	Not enough cooling water

### Note for Engine

There might be a coolant leak in the engine room



Admin. No. 2019010502

\*This report is only for your reference. We are not responsible for the actual condition of checked item.