



# Inspection Report


Inspection Date: 2019/02/18

## Excavators


General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK200-8		
<b>Year</b>	2007		
<b>Hour (h)</b>	3274	<b>Meter</b>	Working
<b>Serial Number</b>	YN11-45827		

Options	
- CAB	- Air conditioner
- Multilever	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		1050		


Note for External Appearance


Undercarriage		
<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	Left	Right
<b>Shoe Width (mm)</b>	600	600
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

Note for Upper Structure


Note for Undercarriage
The shoe links have some kinks


Engine	
<b>Model</b>	J08E-TI
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2019020317