

Inspection Report

Inspection Date: 2024/11/29

Excavators

| General Information | | | |
|---------------------|-----------------|------|---------|
| Maker | KOMATSU | | |
| Model Number | PC30MR-5NO | | |
| Year | 2019 | | |
| Hour (h) | 2253 M e | eter | Working |
| Serial Number | 54263 | | |

Upper Structure

| | | Cylinder | | Play |
|------------|---------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| Boom | Right | No | No | omai |
| | Arm | No | No | Small |
| | Bucket | No | No | Small |
| Bucket Siz | ze (mm) | 410 | | |

Undercarriage

| Steel shoes with rubber pads | |
|------------------------------|--|
| No oil leak | |
| Left | Right |
| 300 | 300 |
| NG | NG |
| ОК | ОК |
| | No oil leak Left 300 NG OK OK OK OK |

| Engine | |
|------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | ОК |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Options - CAB - Multilever

- Blade
- Arm Crane

- Speed changer - Air conditioner

Note for External Appearance

- EPA

- Repainted

- Breaker Pipings

|) |
|---|
| |

| Note for Undercarriage | |
|------------------------|--|
| | |
| | |

| Note for Operating Component | |
|------------------------------|--|
| | |
| | |
| | |
| | |
| Note for Engine | |
| | |



Admin No.

*This report is only for your reference. We are not responsible for the actual condition of checked item.