

Inspection Date: 2017/09/14

General Information		
Maker	YANMAR	
Model Number	ViO20-2	
Year	2003	
Hour (h)	3996 Meter	Working
Serial Number	25669B	

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure					
		Cylinder		Play	
		Oil Leak	Scratch/Rust	гіау	
Boom	Left	No	No	Small	
	Right	N/A	N/A	Oman	
Arm		No	No	Small	
Bucket		No	No	Big	
Bucket Siz	e (mm)	420			

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	

g			
	Left	Right	
Shoe Width (mm)	250	250	
ldler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	
Fusing			

- The rubber shoes have deteriorated	
over time and are worn	
- The right rubber shoe is partly cracked	

Note for Undercarriage





