



# Inspection Report

Inspection Date: 2018/06/15

## Excavators

### General Information

<b>Maker</b>	KUBOTA		
<b>Model Number</b>	RX-403S		
<b>Year</b>	2006		
<b>Hour (h)</b>	3427	<b>Meter</b>	Working
<b>Serial Number</b>	60329		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		540		

### Note for External Appearance

Repainted




### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	300	300
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	NG	NG
<b>Shoe Link</b>	OK	OK


### Note for Upper Structure

- The bucket is partly cracked
- Asphalt is adhered to the bucket (complete washing is not applicable)



### Note for Undercarriage

- Oil oozing from one of the right lower rollers and one of the left lower rollers
- The rubber shoes have deteriorated over time, are worn, and partly cracked




### Engine

<b>Model</b>	D1503-KA
<b>Serial Number</b>	06L1138
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

The seat is partly torn



### Note for Engine



Admin No. 2018061006