



# Inspection Report

Inspection Date: 2018/09/20


## Excavators

General Information			
<b>Maker</b>	KATO		
<b>Model Number</b>	HD820V		
<b>Year</b>	2013		
<b>Hour (h)</b>	1823	<b>Meter</b>	Working
<b>Serial Number</b>	KWJ01E01KD0006788		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
<b>Boom</b>	<b>Left</b>	No	No	No
	<b>Right</b>	No	No	
<b>Arm</b>		No	No	No
<b>Bucket</b>		No	No	Small
<b>Bucket Size (mm)</b>		1030		

**Note for External Appearance**



Undercarriage			
<b>Shoe Type</b>	Steel		
<b>Swing Circle</b>	No oil leak		
	<b>Left</b>	<b>Right</b>	
<b>Shoe Width (mm)</b>	700	700	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

**Note for Upper Structure**




**Note for Undercarriage**




Engine	
<b>Model</b>	4M50-TLE3A
<b>Serial Number</b>	4M50 D82137
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

**Note for Operating Component**



**Note for Engine**

The engine hood cover has been partly repaired



Admin No. 2018090302