



Inspection Report

Inspection Date: 2018/06/14


Excavators

General Information			
Maker	YANMAR		
Model Number	Vio50-5		
Year	2006		
Hour (h)	4818	Meter	Working
Serial Number	50914		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		615		

Note for External Appearance
- The front working lamp is broken
- The rear door does not have a handle




Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	NG	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The bolts of the bucket side cutters are detached




Note for Undercarriage
- The right upper rollers are detached
- The rubber shoes have deteriorated over time, are worn, and partly cracked




Engine	
Model	4TNV88-P
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine
Oil oozing from around the hydraulic pump



Admin No. 2018061051