

Inspection Report

Inspection Date: 2019/03/25

Excavators

| General Information | | |
|---------------------|-------------------|---------|
| Maker | HITACHI | |
| Model Number | ZX120-3 | |
| Year | 2008 | |
| Hour (h) | 4404 Meter | Working |
| Serial Number | HCM1R100J00081748 | |

Upper Structure

| | | Cylinder | | |
|------------------|-------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | Play |
| Boom | Left | No | No | Small |
| | Right | No | No | Smail |
| Arm | | No | No | Small |
| Bucket | | No | No | Big |
| Bucket Size (mm) | | 890 | | |

Undercarriage

| Undercarnage | | |
|-----------------|----------|-------|
| Shoe Type | Steel | |
| Swing Circle | Oil leak | |
| | Left | Right |
| Shoe Width (mm) | 500 | 500 |
| Idler | ОК | ОК |
| Sprocket | ОК | ОК |
| Pin Bush | ОК | ОК |
| Upper Roller | ОК | ОК |
| Track Roller | ОК | ОК |
| Shoe Link | ОК | ОК |

| Engine | |
|------------------|----------------|
| Model | AJ-4JJ1XYSA-03 |
| Serial Number | 4JJ1-110512 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Oil oozing |
| Multi Lever | - |
| | |

Options - Speed changer - CAB - Speed changer - Air conditioner - Air conditioner - EPA - Leve

Note for External Appearance Some side-guard pipes are lost



Note for Upper Structure

Unable to lift up the body with the arm and boom
The edges of the bucket are worn and

damaged



Note for Operating Component

- Rear-view camera
- The surface of the seat is partly torn



Note for Engine

Unusual sound from around the engine pump



Admin No.

2019030878

*This report is only for your reference. We are not responsible for the actual condition of checked item.