| Inspection | Date: | 2024/11/29 |
|------------|-------|------------|
| | | |

| General Information | | |
|---------------------|------------|---------|
| Maker | KOMATSU | |
| Model Number | PC40MR-2 | |
| Year | 2007 | |
| Hour (h) | 2991 Meter | Working |
| Serial Number | 11847 | |

| Options | |
|--------------|-------------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | - Breaker Pipings |
| | |
| - EPA | |

| Upper Structure | | | |
|--------------------------------|------------------------|---|---|
| Cylinder Oil Leak Scratch/Rust | | Cylinder | |
| | | Play | |
| Left | No | No | Small |
| Right | No | No | Oman |
| Arm | No | No | Small |
| Bucket | | No | Small |
| Bucket Size (mm) | | | |
| | Right Arm Bucket | Oil Leak Left No Right No Arm No Bucket No | Oil Leak Scratch/Rust Left No No Right No No Arm No No Bucket No No |

| Note for External Appearance | |
|---|--|
| - The body has some scratches, rust and corrosion - Repainted | |

Note for Upper Structure

| Undercarriage | | |
|-----------------|-------------|-------|
| Shoe Type | Rubber | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 400 | 400 |
| Idler | ОК | OK |
| Sprocket | ОК | OK |
| Pin Bush | ОК | OK |
| Upper Roller | ОК | OK |
| Track Roller | ОК | OK |
| Shoe Link | ОК | ОК |

| Note for Undercarriage | |
|--|--|
| - The travel motor covers are corroded (please check the photos) | |
| | |

| Engine | |
|------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | ОК |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |



