



Inspection Report

Inspection Date: 2019/02/19


Excavators

| General Information | | | |
|---------------------|--------|-------|---------|
| Maker | KUBOTA | | |
| Model Number | U-10-3 | | |
| Year | | | |
| Hour (h) | 4794 | Meter | Working |
| Serial Number | 14326 | | |

| Options | |
|--------------|-----------------|
| - Multilever | - Speed changer |
| - Blade | |


| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | No | Big |
| Bucket Size (mm) | | 345 | | |

Note for External Appearance
The working light is broken




| Undercarriage | | | |
|-----------------|----------|-------|--|
| Shoe Type | Rubber | | |
| Swing Circle | Oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 180 | 180 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure
- Unable to move straight while rotating (it tends to go left)
- The blade is partly deformed




Note for Undercarriage
The right rubber shoe has some cuts



| Engine | |
|------------------|---------------|
| Model | D722 |
| Serial Number | 6R1426 |
| Engine Oil Leak | Oil oozing |
| Engine Oil Gauge | OK |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | Unchecked |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | Unchecked |

Note for Operating Component
The seat is partly torn



Note for Engine



Admin No. 2019020497