



# Inspection Report

Inspection Date: 2024/08/08

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK135SR-2		
<b>Year</b>	2014		
<b>Hour (h)</b>	6235	<b>Meter</b>	Working
<b>Serial Number</b>	YY06-21833		

### Options

- CAB	- Air conditioner
- Multilever	- Pipings
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	890			

### Note for External Appearance

- The body is deteriorated over time




### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	Oil oozing	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure



### Note for Undercarriage




### Engine

<b>Model</b>	D04FR-020050
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	Oil oozing
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Oil oozing
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is torn  
- The cabin inside is rusted



### Note for Engine



Admin No. 3000062808