



# Inspection Report

Inspection Date: 2017/08/07

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	Vio50-5		
<b>Year</b>	2006		
<b>Hour (h)</b>	3880	<b>Meter</b>	Working
<b>Serial Number</b>	50884B		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		620		

### Note for External Appearance

- Repainted
- Has some dents



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	400	400
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Upper Structure

The arm crane hook is lost



### Note for Undercarriage

The rubber shoes have deteriorated over time and have some cracks



### Engine

<b>Model</b>	4TNV88-P
<b>Serial Number</b>	43748
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	N/A
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

Torn seat



### Note for Engine

The lid of the fuel tank is lost



Admin No. 2017080177