



# Inspection Report

Inspection Date: 2018/07/24

## Truck

### General Information

<b>Maker</b>	MITSUBISHI
<b>Model Number</b>	KC-FH227H
<b>Year</b>	1997
<b>Mileage (km)</b>	162430
<b>Serial Number</b>	FH227H-510106

### Note for External Appearance

- Trailer: TADANO ZF304 (FX300 model, S/N: EK0964)
- 4-stage crane (hook-in)
- No remote controller
- The truck bed is damaged and partly broken

### Engine

<b>Model</b>	6D16
<b>Serial Number</b>	6D16-879205
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- F5
- A/C is working
- Retractable mirror

### Note for Engine

Engine power: 170PS

Admin. No. 2018070826

\*This report is only for your reference. We are not responsible for the actual condition of checked item.