



# Inspection Report

Inspection Date: 2022/11/11

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC128US-2E1		
<b>Year</b>	2006		
<b>Hour (h)</b>	9947	<b>Meter</b>	Working
<b>Serial Number</b>	KMTPC039C01010829		

### Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	- Pipings
- Arm Crane	
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	Oil oozing	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	850			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure

The bucket are bent



### Note for Undercarriage



### Engine

<b>Model</b>	SAA4D95LE-3
<b>Serial Number</b>	112624
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Yes
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000043663