



Inspection Report


Inspection Date: 2019/02/22

Excavators


| General Information | | | |
|---------------------|--------|-------|---------|
| Maker | KUBOTA | | |
| Model Number | KH-5H | | |
| Year | | | |
| Hour (h) | 1569 | Meter | Working |
| Serial Number | 10486 | | |


| Options | |
|---------|--|
| - CNP | |
| - Blade | |

| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | Oil leak | Scratch | Small |
| | Right | N/A | N/A | |
| Arm | | No | Scratch | Small |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 350 | | |


| Note for External Appearance |
|---|
|  |


| Undercarriage | | | |
|-----------------|-------------|-------|--|
| Shoe Type | Steel | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 250 | 250 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

| Note for Upper Structure |
|--|
| - Upper structure movement is slow - Oil leak from the swing cylinder and the blade cylinder - The cylinder rods are rusty |
|  |

| Note for Undercarriage |
|---|
| Traveling motion is slow |
|  |

| Engine | |
|------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | Rust/Oil |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | Oil oozing |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Oil oozing |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
|  |

| Note for Engine |
|---|
| Hydraulic oil is not enough |
|  |

Admin No. 2019020502