



# Inspection Report

Inspection Date: 2021/10/07

## Dozer

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	D31PX-21
<b>Year</b>	2011
<b>Hour (h)</b>	4854
<b>Serial Number</b>	KMT0D007J01051333

### Note for External Appearance

- The body is rusty and its paint is peeling off



### Upper Structure

<b>Blade Tilt Cylinder</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Lift Arm Cylinder</b>	No oil leak	No oil leak
<b>Blade Angle Cylinder</b>	No oil leak	No oil leak
<b>Travel Motor</b>	No oil leak	No oil leak

### Note for Upper Structure



### Note for Operating Component

- The seat is partly torn  
- Lights don't work(Control Panel doesn't work)



### Undercarriage

	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	600	600
<b>Idler</b>	OK	OK
<b>Shoe Link</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Pin Bush</b>	OK	OK

### Note for Undercarriage



### Engine

<b>Model</b>	SAA4D102E-2-B
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	Oil shortage
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for Engine

- Could not find out the engine serial number



Admin. No. 3000035678

\*This report is only for your reference. We are not responsible for the actual condition of checked item.