



# Inspection Report


Inspection Date: 2018/12/11

## Excavators


General Information			
<b>Maker</b>	SUMITOMO		
<b>Model Number</b>	SH120-3		
<b>Year</b>	2008		
<b>Hour (h)</b>	5996	<b>Meter</b>	Working
<b>Serial Number</b>	SMT120A3E00SC7779		

Options	
- CAB	- Air conditioner
- Multilever	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		880		


Note for External Appearance
The windows of the cabin are partly broken


Undercarriage		
<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	No oil leak	
	Left	Right
<b>Shoe Width (mm)</b>	500	500
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

Note for Upper Structure


Note for Undercarriage


Engine	
<b>Model</b>	BB-4BC1 TRA
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Unchecked
<b>Multi Lever</b>	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2019010211