



# Inspection Report

Inspection Date: 2024/12/26

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC28UU-2E		
<b>Year</b>	1997		
<b>Hour (h)</b>	5397	<b>Meter</b>	Working
<b>Serial Number</b>	13813		

### Options

- CAB	
- Blade	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil leak	No	Big
Bucket Size (mm)	340			

### Note for External Appearance

- The body has some scratches, rust, corrosion, dents, damages
- VIN plate is dirty
- The door lever is slightly stiff



### Undercarriage

<b>Shoe Type</b>	Rubber		
<b>Swing Circle</b>	No oil leak		
		Left	Right
Shoe Width (mm)	300	300	
Idler	NG	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

### Note for Upper Structure



### Note for Undercarriage

- The left travel motor cover is corroded



### Engine

<b>Model</b>	3D82AE-3D
<b>Serial Number</b>	09009
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Unchecked
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	-

### Note for Operating Component

- The seat is torn



### Note for Engine



Admin No. 3000067639