



# Inspection Report

Inspection Date: 2018/07/24

## Truck

### General Information

<b>Maker</b>	MITSUBISHI
<b>Model Number</b>	KC-FE517BD
<b>Year</b>	1996
<b>Mileage (km)</b>	101542
<b>Serial Number</b>	FE517BD-522245

### Note for External Appearance

- The movement of the truck bed is NOT checked
- 3-way dump truck
- ShinMaywa DT2-38SAY

### Engine

<b>Model</b>	4D33
<b>Serial Number</b>	-
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- F5
- A/C is broken

### Note for Engine

Admin. No. 2018070824

\*This report is only for your reference. We are not responsible for the actual condition of checked item.