



# Inspection Report

Inspection Date: 2019/05/16

## Excavators


General Information			
<b>Maker</b>	SUMITOMO		
<b>Model Number</b>	SH125X-3B		
<b>Year</b>	2008		
<b>Hour (h)</b>	2294	<b>Meter</b>	Working
<b>Serial Number</b>	SMT125X3L00SC7105		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		895		

**Note for External Appearance**


The left and right frames have some dents



Undercarriage		
<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	No oil leak	
	Left	Right
<b>Shoe Width (mm)</b>	500	500
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK


**Note for Upper Structure**

The bucket is worn




**Note for Undercarriage**

- One of the left track links has kinks
- One of the right track links has kinks
- The rubber pads are worn




Engine	
<b>Model</b>	AJ-4JJ1XYSS-02
<b>Serial Number</b>	4JJ1-105809
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

**Note for Operating Component**



**Note for Engine**

Oil oozing from the engine head



Admin No. 2019050429