



Inspection Report

Inspection Date: 2018/09/23


Excavators

| General Information | | | |
|----------------------|-------------|--------------|---------|
| Maker | KOMATSU | | |
| Model Number | PC138US-2E1 | | |
| Year | 2005 | | |
| Hour (h) | 8858 | Meter | Working |
| Serial Number | 6188 | | |

| Options | |
|--------------|-----------|
| - CAB | - Pipings |
| - Multilever | |
| - EPA | |


| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | No | No | |
| Arm | | No | No | Small |
| Bucket | | No | Yes | Big |
| Bucket Size (mm) | | | | |

Note for External Appearance
The left side cover has some dents




| Undercarriage | | | |
|------------------------|------------------------------|-------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | Oil oozing | | |
| | Left | Right | |
| Shoe Width (mm) | | | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure
- No standard bucket
- The arm and the boom are partly cracked




Note for Undercarriage
- The rubber pads are worn and some of them have been detached
- Oil oozing from around the swivel and the right travel motor
- Traveling motion is slightly slow (unable to check enough)




| Engine | |
|-------------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Oil oozing |
| Multi Lever | No oil leak |

Note for Operating Component
The air conditioner makes a motor sound



Note for Engine
- Unusual sound from the hydraulic pump
- No battery



Admin No. 2018090341