



# Inspection Report

Inspection Date: 2018/07/23

## Truck

### General Information

<b>Maker</b>	ISUZU
<b>Model Number</b>	KK-FK71GC
<b>Year</b>	2001
<b>Mileage (km)</b>	126455
<b>Serial Number</b>	FK71GC-751128

### Note for External Appearance

Trailer: KYOKUTO DDO4-35

### Engine

<b>Model</b>	6D61
<b>Serial Number</b>	*36817
<b>Engine Oil Leak</b>	No
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for Control Panel

- The roof of the cabin has some dents
- The air conditioner is broken and won't produce air
- F6

### Note for Engine

Admin. No. 2018070767

\*This report is only for your reference. We are not responsible for the actual condition of checked item.