



# Inspection Report

Inspection Date: 2019/02/08

## Excavators

### General Information

<b>Maker</b>	KUBOTA		
<b>Model Number</b>	U-30-3S		
<b>Year</b>	2005		
<b>Hour (h)</b>		<b>Meter</b>	#N/A
<b>Serial Number</b>	60874		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	428			

### Note for External Appearance

- The body is rusty and decayed
- The left side of the body has some dents



### Undercarriage

<b>Shoe Type</b>	Rubber		
<b>Swing Circle</b>	No oil leak		
		Left	Right
<b>Shoe Width (mm)</b>	300	300	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

### Note for Upper Structure

- The hoses of the breaker pipes have deteriorated over time and are partly deformed
- The bucket teeth are worn



### Note for Undercarriage

- The rubber shoes have deteriorated over time and are worn



### Engine

<b>Model</b>	D1503
<b>Serial Number</b>	05S0679
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Unchecked
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	N/A
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is partly cracked
- The hour meter has been replaced (2183h+1322h)



### Note for Engine

- The muffler has deteriorated over time and has some holes
- The muffler is partly cracked
- There is a history of engine overheating



Admin No. 2019020027