



# Inspection Report

Inspection Date: 2024/08/08

## Wheel Loader

### General Information

Maker	YANMAR
Model Number	V3-5B
Year	2006
Hour (h)	2661
Serial Number	L3DA-53801

### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

### Engine

Model	3TNV84-XKAH
Serial Number	30859
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for External Appearance

- Repainted
- The cabin is rusty and corroded
- The right and left side step of the cabin is corroded



### Note for Upper Structure



### Note for Operating Component

- With CAB (cabin) heater



### Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



### Note for Engine

- EPA



Admin. No. 3000062480

\*This report is only for your reference. We are not responsible for the actual condition of checked item.