



# Inspection Report

Inspection Date: 2019/02/18

## Excavators

### General Information

<b>Maker</b>	CAT		
<b>Model Number</b>	308CCR		
<b>Year</b>	2006		
<b>Hour (h)</b>	1808	<b>Meter</b>	Working
<b>Serial Number</b>	CPE03422		

### Options

- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
<b>Boom</b>	<b>Left</b>	Oil oozing	No	Small
	<b>Right</b>	N/A	N/A	
<b>Arm</b>		No	No	No
<b>Bucket</b>		No	No	Big
<b>Bucket Size (mm)</b>	720			


### Note for External Appearance



### Undercarriage


<b>Shoe Type</b>	Steel shoes with rubber pads			
<b>Swing Circle</b>	No oil leak			
		Left	Right	
<b>Shoe Width (mm)</b>	450	450		
<b>Idler</b>	OK	NG		
<b>Sprocket</b>	OK	OK		
<b>Pin Bush</b>	OK	OK		
<b>Upper Roller</b>	OK	OK		
<b>Track Roller</b>	OK	OK		
<b>Shoe Link</b>	OK	OK		

### Note for Upper Structure



### Note for Undercarriage


- The shoe links are partly loose  
 - Oil oozing from the reduction drive of the right travel motor



### Engine

<b>Model</b>	4M40-E1
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Normal
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 2019020346