

# ZX135US Hydraulic Shovel

2019/12/26

## BASIC INFORMATION

Inspection Date		Model	ZX135US	Serial No.	71872
Date of Manufacture		Hourmeter	9239 HR	Condition of Hourmeter	
Hourmeter (Estimated)		Engine No.	6SZXL04.3GXA	Job Status	Rental
Accident History		Cabin/Canopy	Cabin	Cabin Type	Standard
Front Attachment	Standard	Super long length(m)		Type of Shoe	Grouser
Width of Track Shoe	500	Bucket/Attachment	Standard BK	Stamp	
Others	Air Conditioner, ML Crane, Multi Lever				

## OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Swing	Normal
Wear: Swing Bearing	Slight	Traveling	Normal	Front Attachment	Normal
Pump Device	Normal				

## UNDERCARRIAGE/CHASSIS/TIRES

Seize: Track Links	No	Wear: Track Link Extension (Right)	Excessive	Wear: Track Link Extension (Left)	Moderate/Within Service Limit
Wear: Track Link Tread(Right)	Slight	Wear: Track Link Tread(Left)	Slight	Wear: Track Link Pins (Right)	Slight
Wear: Track Link Pins (Left)	Slight	Wear: Track Shoe/Rubber Shoe	Slight	Bent/Broken/Missing: Track Shoe	No
Wear: Rubber Pad		Broken/Missing: Rubber Pad		Missing: Rubber Pad	
Broken/Crack: Rubber Shoe(Right)		Broken/Crack: Rubber Shoe(Left)		Missing: Rubber Shoe Core	
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken/Missing: Rollers	None	Wear: Front Idler(Right)	Slight	Wear: Front Idler(Left)	Slight
Wear: Sprocket(Right)	Slight	Wear: Sprocket(Left)	Slight	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No				

## FRONT & PINS

Boom	Normal	Arm	Normal	Wear: Boom Foot Pin	Moderate/Within Service Limit
Wear: Boom/Arm Joint Pin	Slight	Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Slight
Wear/Deformation: Bucket	Good	Wear/Deformation: Blade			

## OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Boom Cylinder(Right)	No	Oil Leak: Boom Cylinder(Left)	No
Oil Leak: Arm Cylinder(Right)	No	Oil Leak: Arm Cylinder(Left)	No	Oil Leak: Bucket Cylinder(Right)	No
Oil Leak: Bucket Cylinder(Left)	No	Oil Leak: Offset Cylinder		Oil Leak: Blade Cylinder	
Oil Leak: Engine	No	Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Oil Leak: Pilot Valve	No	Oil Leak: Center Joint	No	Oil Leak: Swing Device	No
Oil Leak: Pump Device	Slight Film				

## APPEARANCE

Engine Cover	Rusted/Corroded	Side Covers	Deformed/Dent, Rusted/Corroded	Under Covers	Rusted/Corroded
Counter Weight	Rusted/Corroded	Main frame	Rusted/Corroded	D Frame	Good Condition
Track Frame	Rusted/Corroded	Cabin	Rusted/Corroded	Door	Stiff Hinges, Not Close Properly

## INTERIOR

Cabin Interior	Good Condition	Seat	Dirty, Torn	Console	Faded
Air conditioner	Malfunction	Freon gas inspection	Good Condition		

## OVERALL RATING

Appearance Evaluation	Fair	Rust/Corrosion	Moderate	Overall Rating	Fair
Special Notes	工具箱側の作業灯点灯しない 後ろエアコン効きが悪い 左後ステップ変形 右前ステップなし サクションホース油にじみ				