



Inspection Report

Inspection Date: 2024/07/18

Excavators

General Information

Maker	KUBOTA		
Model Number	U40-6		
Year	2014		
Hour (h)	3847	Meter	Working
Serial Number	13126		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		Oil oozing	No	Big
Bucket		No	Yes	Big
Bucket Size (mm)	520			

Note for External Appearance

- The covers have rust, scratches, and dents



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- The blade has some dents and bends
- Oil oozing from the blade cylinder



Note for Undercarriage

- Some rubber pads are worn and broken
- Oil oozing from the reduction drive covers of the travel motor



Engine

Model	V2607
Serial Number	8EJ1661
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- The arm crane has some problems



Note for Engine

- Slight blow-by



Admin No. 3000061121