



Inspection Report

Inspection Date: 2019/02/08

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-20-3S		
Year	2006		
Hour (h)		Meter	#N/A
Serial Number	10871		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		600		

Note for External Appearance


- The body is rusty and damaged
- The right side of the body has some dents
- The bucket cylinder seals are deteriorated over time



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

- Oil leak from the right control lever
- No standard bucket
- This machine will be sold with the bucket in the picture



Note for Undercarriage


The rubber shoes are worn



Engine	
Model	D1105
Serial Number	6W8050
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak


Note for Operating Component

- The seat is partly cracked
- The hour meter has been replaced (914h+4218h)



Note for Engine

Oil oozing from around the engine oil element



Admin No. 2019020026