



# Inspection Report

Inspection Date: 2019/05/19

## Dozer

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	D31PX-22
<b>Year</b>	2008
<b>Hour (h)</b>	3676
<b>Serial Number</b>	60105

### Note for External Appearance

600T, CNP, 6-way dozer



### Upper Structure

<b>Blade Tilt Cylinder</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Lift Arm Cylinder</b>	No oil leak	No oil leak
<b>Blade Angle Cylinder</b>	No oil leak	No oil leak
<b>Travel Motor</b>	No oil leak	No oil leak

### Note for Upper Structure



### Note for Operating Component

The roof is partly decayed



### Undercarriage

	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	600	600
<b>Idler</b>	OK	OK
<b>Shoe Link</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Pin Bush</b>	OK	OK

### Note for Undercarriage



### Engine

<b>Model</b>	SAA4D95LE-5-A
<b>Serial Number</b>	504443
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for Engine

EPA



Admin. No. 2019050597

\*This report is only for your reference. We are not responsible for the actual condition of checked item.