



# Inspection Report

Inspection Date: 2024/08/08

## Wheel Loader

### General Information

<b>Maker</b>	YANMAR
<b>Model Number</b>	V3-5B
<b>Year</b>	2006
<b>Hour (h)</b>	3248
<b>Serial Number</b>	L3DA-53779

### Note for External Appearance

- The bucket is repainted



### Upper Structure

<b>Lift Arm Cylinder (Left)</b>	No oil leak
<b>Lift Arm Cylinder (Right)</b>	No oil leak
<b>Bucket Cylinder (Left)</b>	No oil leak
<b>Bucket Cylinder (Right)</b>	No oil leak

### Note for Upper Structure



### Undercarriage

<b>Front Accel</b>	No oil leak
<b>Rear Accel</b>	No oil leak

### Note for Operating Component

- With CAB (cabin) heater  
- The right and left side step of the cabin is corroded



### Engine

<b>Model</b>	3TNV84-XKAH
<b>Serial Number</b>	30692
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Water Pump</b>	No water leak
<b>Radiator</b>	OK

### Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.



### Documents

<b>Automobile Inspection Certificate</b>	No
--	----

### Note for Engine

- EPA



Admin. No. 3000062476

\*This report is only for your reference. We are not responsible for the actual condition of checked item.