



# Inspection Report

Inspection Date: 2024/05/18

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC40MR-3		
<b>Year</b>			
<b>Hour (h)</b>	4449	<b>Meter</b>	Working
<b>Serial Number</b>	KMTPC203E04018544		

### Options


- CNP	- Speed changer
- Multilever	
- Blade	- PIPINGS

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	510			

### Note for External Appearance

- The covers have some rust and dents  
 - Some covers are missing



### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
Shoe Width (mm)	350	350
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


### Note for Upper Structure

- Oil oozing from the bottom  
 - The blade is distorted



### Note for Undercarriage

- The rubber pads are missing



### Engine

<b>Model</b>	4D88E-68PDA
<b>Serial Number</b>	22059
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The seat is torn



### Note for Engine



Admin No. 3000058693