



# Inspection Report

Inspection Date: 2019/02/08

## Excavators


General Information			
Maker	KUBOTA		
Model Number	U-30-5		
Year	2011		
Hour (h)	5058	Meter	Working
Serial Number	72683		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		670		

**Note for External Appearance**


- The right side of the body has some dents
- The boom cylinder covers have some play
- The hinge of the engine cover is broken
- The right side of the engine cover has some dents



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


**Note for Upper Structure**

- Oil oozing from the hydraulic pump adaptor
- Oil leak from around the control valve
- The bottom of the bucket is worn
- No standard bucket
- This machine will be sold with the bucket in the picture




**Note for Undercarriage**

The rubber shoes are worn



Engine	
Model	D1703
Serial Number	AY1347
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	Unchecked
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	N/A
Multi Lever	No oil leak

**Note for Operating Component**



**Note for Engine**

Engine oil is old



Admin No. 2019020028