



# Inspection Report


Inspection Date: 2023/12/01

## Excavators


General Information			
Maker	KOMATSU		
Model Number	PC38UU-5		
Year	2014		
Hour (h)	3874	Meter	Working
Serial Number	KMTPC220LEE016343		


Options	
- CNP	- Speed changer
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		520		


Note for External Appearance
- The left cover is missing


Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	NG	NG	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
- The idlers are worn


Engine	
Model	3D88E-6BPCB
Serial Number	26341
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 3000053519