



# Inspection Report

Inspection Date: 2022/09/17

## Excavators

### General Information

<b>Maker</b>	KOMATSU		
<b>Model Number</b>	PC200-8N1		
<b>Year</b>	2009		
<b>Hour (h)</b>	9035	<b>Meter</b>	Working
<b>Serial Number</b>	KMTPC197L02315905		

### Options

- |              |                   |
|--------------|-------------------|
| - CAB        | - Speed changer   |
| - Multilever | - Air conditioner |
| - Arm Crane  |                   |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		Oil leak	Yes	Big
Bucket Size (mm)	1030			

### Note for External Appearance

- The covers are damaged and have some dents
- The cabin handrail is bent



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
<b>Shoe Width (mm)</b>	700	700
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	NG
<b>Shoe Link</b>	OK	OK

### Note for Upper Structure

- The tip of the arm has some dents
- The bucket is cracked
- The boom has welding repair marks
- The bolts of the bucket side cutters are missing



### Note for Undercarriage

- The right lower rollers are missing



### Engine

<b>Model</b>	SAA6D107E-1
<b>Serial Number</b>	26543581
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	Yes
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

- The air conditioner is broken



### Note for Engine



Admin No. 3000042427