



# Inspection Report

Inspection Date: 2024/07/12

## Excavators

### General Information

<b>Maker</b>	KUBOTA		
<b>Model Number</b>	RX-306		
<b>Year</b>	2012		
<b>Hour (h)</b>	5235	<b>Meter</b>	Working
<b>Serial Number</b>	11993		

### Options

- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	430			

### Note for External Appearance

- Repainted  
- The body has some dents



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


### Note for Upper Structure

- No side cutter



### Note for Undercarriage

- Oil oozing from the right travel motor



### Engine

<b>Model</b>	
<b>Serial Number</b>	7CL1130
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	Oil oozing
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak


### Note for Operating Component

- The seat is torn



### Note for Engine

- Oil oozing from the control valve



Admin No. 3000059653