



Inspection Report

Inspection Date: 2018/03/02


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-15-3S		
Year	2006		
Hour (h)	-	Meter	Not Working
Serial Number	42329		

Options	
- Multilever	- Speed changer
- Blade	- Breaker Piping


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	Yes	No
Bucket Size (mm)		400		

Note for External Appearance
- Repainted
- No canopy
- The working lamps are broken
- The side covers and the engine cover have been replaced with new ones




Undercarriage			
Shoe Type	Rubber		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	230	230	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The bucket cylinder has small scratches
- The arm is reinforced




Note for Undercarriage
- The rubber shoes have deteriorated over time and are partly damaged
- Width adjustable




Engine	
Model	D782-K3A
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
Though the hour meter is unchecked, it is more than 3722h as of December 2017 (according to the seller)



Note for Engine
The engine, starter, and radiator have been replaced with new ones



Lot No ARA013-0043 Admin No. 2018020536