



Inspection Report

Inspection Date: 2019/05/13


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-40-5		
Year	2007		
Hour (h)	3218	Meter	#N/A
Serial Number	70037		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		540		

Note for External Appearance
The caution plate seal is partly torn




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage


- The sprockets are rusty
- The rubber pads have deteriorated over time



Engine	
Model	V2203
Serial Number	7J3233
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	Oil oozing

Note for Operating Component

- The seat is partly torn
- The hour meter has been replaced (484+2734h)



Note for Engine



Admin No. 2019050296