



Inspection Report


Inspection Date: 2017/08/07

Excavators


| General Information | | | |
|---------------------|---------|-------|---------|
| Maker | KUBOTA | | |
| Model Number | RX-403S | | |
| Year | 2005 | | |
| Hour (h) | 2586 | Meter | Working |
| Serial Number | 60139 | | |


| Options | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

| Upper Structure | | | | |
|------------------|-------|------------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | Oil oozing | No | Big |
| Bucket Size (mm) | | 550 | | |


| Note for External Appearance |
|---|
| Repainted |
|  |

| Undercarriage | | | |
|-----------------|-------------|-------|--|
| Shoe Type | Rubber | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 300 | 300 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

| Note for Upper Structure |
|---|
| The dust seal of the bucket cylinder is partly damaged |
|  |

| Note for Undercarriage |
|---|
| Oil oozing from 2 of the lower rollers |
|  |

| Engine | |
|------------------|---------------|
| Model | D1503 |
| Serial Number | 05Q0135 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | Oil oozing |

| Note for Operating Component |
|---|
|  |

| Note for Engine |
|---|
|  |

Admin No. 2017080143