

Inspection Report

Inspection Date: 2018/10/15

Excavators

| General Information | | |
|---------------------|------------|---------|
| Maker | KUBOTA | |
| Model Number | U-30-5 | |
| Year | 2011 | |
| Hour (h) | 2845 Meter | Working |
| Serial Number | 73088 | - |

Upper Structure

| | | Cylinder | | Play |
|------------|----------------------|----------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | oman |
| | Arm | No | No | Small |
| Bucket | | No | No | Small |
| Bucket Siz | Bucket Size (mm) 420 | | | |

Undercarriage

| Steel shoes with rubber pads | |
|------------------------------|--|
| No oil leak | |
| Left | Right |
| 300 | 300 |
| ОК | ОК |
| | No oil leak Left 300 OK OK OK OK |

| Engine | |
|------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | ОК |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | ОК |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | - |
| | |

| Options | |
|-------------|-----------------|
| - CNP | - Speed changer |
| | |
| - Blade | |
| - Arm Crane | |
| | |

Note for External Appearance



Note for Upper Structure

The blade is partly deformed



| Note for Operating Component | |
|---------------------------------------|--|
| Note for Operating Component | |
| | |
| | |
| | |
| | |
| Note for Engine | |
| The parts around the hood are damaged | |



Admin No.

2018100053

*This report is only for your reference. We are not responsible for the actual condition of checked item.