

# **Inspection Report**

#### Inspection Date: 2019/03/25

# **Excavators**

General Information				
Maker	KOBELCO			
Model Number	SK200-8			
Year	2011			
Hour (h)	4830 Meter	Working		
Serial Number	YN12-59973	-		

#### **Upper Structure**

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	omai
	Arm	No	No	Small
Bucket		No	Yes	Big
Bucket Size (mm)		1040		

#### Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	EA-J05E-TA
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Oil oozing
Multi Lever	No oil leak

# Options - CAB - Speed changer - Multilever - Air conditioner - Arm Crane - EPA

### Note for External Appearance

- The body is rusty damaged by salt
- (check the pictures)
- The VIN is partly unclear
- The right side cover has some dents



#### Note for Upper Structure


- 1 side of the arm has been reinforced
- The side of the arm is partly deformed
- The bottom of the bucket has some
- dents, is partly worn and deformed



## Note for Undercarriage

The track frame is rusty





- The tip of the muffler is rusty and
- damaged
- The engine is damaged by salt

Admin No. 2019030877

\*This report is only for your reference. We are not responsible for the actual condition of checked item.