



Inspection Report


Inspection Date: 2018/03/02

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-40-3S		
Year	2006		
Hour (h)	5306	Meter	Working
Serial Number	30777		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pippings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		550		


Note for External Appearance
The side covers have some scratches



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Oil oozing from the blade hose


Note for Undercarriage
- Oil oozing from the travel motors
- Oil oozing from one of the left lower rollers and one of the right lower rollers
- The rubber pads have deteriorated over time and are partly worn


Engine	
Model	V2203KA
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine
- Oil oozing from around the hydraulic control valve
- The muffler is rusty


Lot No ARA013-0046 Admin No. 2018020538